	Approved For Release 2002/06/24 : CIA-RDP99B00048R000100030003-2 JOINT MESSAGEFORM SECRET
	SPACE BELOW RESERVED FOR COMMUNICATION CENTER
	10/02207
	PRECEDENCE TYPE MSG (Check) ACCOUNTING ORIG. OR REFERS TO CLASSIFICATION OF REFERENCE
_	FO ROUTINE BOOK MULTI SINGLE
7 F	ROM: SPECIAL INSTRUCTIONS
7	D:
_	Logs
*	
2	PROM
]	L. VISIT TO PROVIDED AN OPPORTUNITY TO HAVE A LOOK AT CURRENT
S	STATUS OF FACILITIES WITH AND DISCUSS OTHER PROGRAMMED
VE.	· .
Ħ	VORK. THE FOLLOWING SUMMARY IS SUBMITTED ON AREAS MOST DIRECTLY
A	AFFECTED BY OUR FUTURE UTILIZATION.  UBT WALLY COMPLETE ON RET
A	. HUN UP PAD LOCATED AT WEST END OF HANGAR IS FIRSHED, TIE DOWN
E	
£	OR ENGINE RUN-UP IS IN PLACE AND THE BLAST FENCE DEFLECTOR IS
C	OMPLETE. THE METAL COVER FOR THE UTILITY DITCH PARALLEL TO HANGAR
D	OORS PLUS PREPARATION OF SHOULDERS IS ALL THAT IS REMAINING TO
٠	OMPLETE THE JOB. THE RUN-UP PAD LOOKS EXCELLENT.
В	LEAN-TO SHED ON NORTH SIDE OF HANGAR IS IN VERY EARLY STAGE. ON
8	DEC INITIAL PREPARATION OF SUB SURFACE FOR CONCRETE PAD WAS IN PROGRESS
•	. HANGAR DOORS HAVE BEEN REWORKED AND ARE APPARENTLY SATISFACTORY. DATE TIME
0	• SHOP SPACE ON SOUTH SIDE OF HANGAR IS SATISFACTORY BUT WILL BE MONTH YEAR
Ū	MPROVED WHEN PAINTING AND OTHER MINOR REPAIRS AME COMPLETE. HEC 64
	25X1A
	TYPED NAME AND TITLE (Signature, if required)
	PHONE PAGE NR. OF NR. PAGES SECURITY CLASSIFICATION  RETURN TYPED  TYPED
	SECURITY CLASSIFICATION E FETACHMENT Commander

25X1A

<u>25</u>X1A

25X1A

25X1A

25X1A

25X1A

	SECURITY CLASSIFICATION	
JOINT MESSAGEFORMOR CONTRACTATION OSHEET: C	IA-RDP99B00048R000400030003-2	
W		
HANGAR ROOF IS BEING PATCHED BUT SO	ME BELIEVE THIS IS WASTED	
EFFORT AND I AGREE.		
security post	IS COMPLETE EXCEPT FOR A	
MINOR MOD.		
G. ELECTRICAL POWER IS NOW AVAILABLE F	ROM THREE COMPATIBLE	
GENERATORS WHICH SHOULD HANDLE T	HE LOAD PLUS PROVIDED BACK	
JP.		
H. TAXIWAY TO RAMP WORK DELAYED PER HO	INSTRUCTIONS, CONDITION IS	
SATISFACTORY FOR USE.		
4 , ·	EN RECEIVED ON INSTALLATION	
OF 4 INCH LINE AND UNDERGROUSD STOPAGE		
YET BEEN LET. THE WELL IN UNUSUABLE DU		4
FILLED THE HOLE BELOW APPROX 65 PT LEVE		
THAT IT COULD BE RECLAIMED BY CLEANING	OUT: AND INSTALLING CASING.	
J. HOUSING IS ESSENTIALLY SAME.		The second of the second
2. CURRENT CONSTRUCTION PLANS FOR NEW	LEAN-TO TO SHED ON NORTH SIDE	
OF HANGAR IS TO POUR CONCRETE PAD 12 F.	f 4 IN WIDE FOR FULL LENGTH OF	
BUILDING (APPROX 135 FT) BUT CURRENT A	UTH OF	25X1A
7267 WILL PROVIDE SHED LESS THAN HALF	OF TOTAL LENGTH. A REQUIRED	The second second
ELECTRIC PANEL BOX ALONE WILL		
3. IN VIEW OF PLANNED UTILIZATION OF	SHED FOR STORAGE OF STAGING	
EQUIPMENT, STRONGLY RECOMMEND THAT SUF	FICIENT FUNDS BE PROVIDED	
FOR COMPLETION OF LEAN-TO FOR THE FULL	LENGTH OF THE HANGAR.	
ENGINEERS ADVISE IT WILL BE NECESSARY	TO LOCATE LATRINE IN THIS	
AREA DUE TO DRAINAGE PROBLEMS ON OTHER		
BOL PAGE NR	NR OF SECURITY CLASSIFICATION PAGES	INITI

25X1A

25X1A

25X1A

ILLEGIB

25X1A

05.744	JOINT MASSAGEFORMOR CONTRACTATION OSMENT: CIA-RDP99B00048R000400030003-2
25X1A	FROM:
	CKCOME
1	OFFICE 12 FT X 12 FT IS PLANNED. THE AREA REMAINING WILL NOT BE
	SUFFICIENT FOR STORAGE OF STAGING GEAR. ESTIMATES THAT 25X1A
25X1A	A TOTAL OF APPROX ADDITIONAL WILL COVER THE
والناء والمالية	ENTIRE JOB.
	4. FURTHER RECOMMEND THAT A CAPABLE ENGINEER DETERMINE NECESSARY
	ACTION TO PROVIDE A SUITABLE ROOF FOR THE HANGAR. IT SEEMS LIKELY
	THAT A NEW ROOF WILL BE REQUIRED. WITH ANTICIPATED FUTURE UTILIZATION
	OF HANGAR FOR STORAGE OF STAGING EQUIPMENT IT IS NECESSARY THAT
	DRY STORAGE BE PROVIDED DURING THE MONSOON SHASON.
	5. CONSIDERABLE PROGRESS HAS BEEN MADE SINCE MY LAST VISIT AND
25X1A	WISH TO COMPLIMENT FOR IMPROVEMENTS MADE.
25X1A	6. ASSISTANCE AND HOSPITALITY PROVIDED IN MOVING
25X1A	PERSONNEL AND EQUIPMENT THRUUAREA APPRECIATED.
	END OF MESSAGE
hina di Angabatan da kanan da	
	SYMBOL PAGE NR OF SEGURITY CLASSIFICATION INITIALS

DD: PORM 55 173-1

☆ U. S. GOVERNMENT PRINTING OFFICE: 1961-8966

SECRET